April 25, 2016

United States Environmental Protection Agency Air Compliance Branch 290 Broadway, 21st Floor New York, NY 10007-1866

Attn:

NESHAP COORDINATOR

Re:

LAGUARDIA AIRPORT – HANGAR 7 SOUTH, VACANT OFFICE

SPACE (BUILD-OUT)

OPERATOR PROJECT #: 217.849

Dear Madam/Sir:

Our NON-RACM courtesy notification for the asbestos abatement work to be done at the above referenced location is attached.

If you have any questions, please contact me at 201-595-4881.

Sincerely,

Uday Mehta, Manager

Environmental field Operations
Construction Management Division

cc:

Project File (EPA-2449)

NON-RACM Notification File

UM/fl

U.S. Environmental Protection Agency Notification of Demolition and Renovation

i e						
Operator Project #: 217.849 Post	mark:	Date Receive	ed: 04/25/2016	Notification	on #: EPA-2449	
I. Type of Notification (O=Original R=Revised C	=Canceled) O					
II. Facility Information (Identify owner, removal co	ontractor, and other	operator)				
Owner Name: THE PORT AUTHORITY OF I	NY & NJ				***************************************	
Address: 241 ERIE ST. ROOM 236		*				
City: JERSEY CITY		State: NJ		Zip: 07310		
Contact: F.DAMBREVILLE, FACILITY	F.DAMBREVILLE, FACILITY SUPERVISOR, ENVIRONMENTAL FIELD OPS			Telephone: 718-533-4053		
Removal Contractor: FIBER CONTROL INC.				•		
Address: 3010 BURNS AVENUE						
City: WANTAGH		State: NY		Zip: 11793		
Contact: EUGENIA PANTONY				Telephone	: 516-781.3000	
Other operator: N/A				relephone	. 010101.0000	
Address:						
City:		State:		Zip:		
Contact:				Telephone:		
III. Type of Operation (D=Demo O=Ordered D	lemo R=Renovativ	on E-Emorgono	v) D	relephone.		
IV. Is Asbestos Present? (Yes/No) YES	ono n-nenovano	on L-Emergenc	у) Б			
V. Facility Description (include building name	number floor	nd for room num	ah a wh			
Building Name: LAGUARDIA AIRPORT	, namber, noor, ar	na 701 100111 Hull	iber):			
Address:						
City: FLUSHING		Ptoto NV				
	HANGAR 7 SOUTH, SECOND FLOOR, VACANT OFFICE SPACE					
Building Size: N/A						
Present Use: VACANT		of Floors:2		Age in Years:	40+	
VI. Procedure, Including Analytical Method, If	Appropriate, Used	Prior I	Use: OFFICE SPA	ACES		
BULK SAMPLING WITH TEM ANALYSIS			reseries of Asp	estos Materiai:		
VII. Approximate Amount of Asbestos, Including:			Nonfriable Asbestos Materials			
Regulated ACM to be Removed	d ACM to be Removed Non-RACM R	l l	e Removed	emoved		
 Category I ACM Not Removed Category II ACM Not Removed 	To Be Removed	Be Removed	Cat I	Cat II	Indicate Measurement	
Diagram and the second			- Out 1	Cat II		
Pipes ROOF FLASHING, PIPE, FITTINS	260 LN FT				Lnft: 260	
Surface Area VAT,DUCT INSULATION	500 SQ FT				Sqft: 500	
Vol RACM Off Facility Component					Cuft: 0	
/III. Scheduled Dates Asbestos Removal		Start: 05/	/05/2016	Complete: 11	1/30/2016	
X. Scheduled Dates Demo\Renovation		Start:		Complete:		
				Complete:		

U.S. Environmental Protection Agency Notification of Demolition and Renovation

X. Description REMOVAL US	n of Planned Demolition or Renovation Wor SING WET METHOD WITH SURFACE AND ISOLA	k, and Method(s) to Be Used: TION BARRIERS			
DUST CONTO	on of Work Practices and Engineering Cont molition And Renovation Site: DL USING WET METHOD ISOLATION AND SURF RS. WET REMOVAL AS PER NEW YORK STATE	ACE BARRIER. ENGINEERING CONT			
XII. Waste Tra	nsporter #1				
Name:	ASBESTOS TRANSPORTATION COMPANY, IN	C.			
Address:	2 MORICHES MIDDLE ISLAND ROAD				
City:	SHIRLEY	State: NY	Zip: 11967		
Contact:	GARY CRETTY		Telephone: 631-924-5050		
Waste Trai	nsporter #2		relephone, 001-024-0000		
Name:	N/A				
Address:					
City:		State:	Zip:		
Contact:			Telephone:		
XIII. Waste Dis	posal Site		Тегериене		
Name:	SOUTHERN ALLEGHENIES LANDFILL				
Location:	CONEMAUGH TOWNSHIP				
City:	DAVIDVILLE	State: PA	Zip: 15928		
	e:814-479-2537		•		
XIV. If Demoliti	ion Ordered By a Government Agency, Plea	ase Identify the Agency Below			
Name:		Title:			
Authority:					
Date of Or	rder: Date Ordered To Begin:				
XV. For Emerg	ency Renovations				
Date and Ho	ur of Emergency:				
	of Sudden or Unexpected Event:				
Explanation of	f How the Event Caused Unsafe Conditions or W	ould Cause Equipment Damage or a	n Unreasonable Financial Burden:		
IMMEDIATE IS	ns of Procedures to Be Followed in the Eve Material Becomes Crumbled, Pulverized or OLATION OF THE AREA AND ADEQUATE WETT FFECTED AREAS	Reduced to Powder:			
(VII. I Certify Th Demolition for inspect	at an Individual Trained in the Provisions of Thi or Renovation And Evidence That the Required ion	s Regulation (40 CFR Part 61, Subpar Training Has Been Accomplished by	This Person Will Be Available		
VIII. I Cerify Tha	at the Above Information Is Correct.	(Signature of Owner	14-25-16		
	The state of the s				